

LAMPIRAN

Proses perakitan dan pengujian alat

(Proses Pengujian Rangkaian Logika)



(Proses Pengujian Kinerja Pompa)



(Proses Pengujian Sensor Ultrasonik)

```
CCMS
Send
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :11cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :11cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :10cm | Hasil Sensor 2 :10cm
Hasil Sensor 1 :11cm | Hasil Sensor 2 :10cm
Autoscroll Show timestamp Both HL & CR 115200 baud Clear output
```



(Proses Pengujian Sensor Ultrasonik Dengan Pompa)

```
Windows Taskbar
Send
Hasil Sensor 1 :34cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :35cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :34cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :35cm | Hasil Sensor 2 :34cm
Hasil Sensor 1 :35cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :35cm | Hasil Sensor 2 :33cm
Hasil Sensor 1 :35cm | Hasil Sensor 2 :34cm
Autoscroll Show timestamp Both HL & CR 115200 baud Clear output
```

(Proses Pengujian Sensor Ultrasonik Membaca Manusia)

